



EVOTECH®
P E R F O R M A N C E

Suzuki GSXR1000

Radiator Guard

Installation Instructions




Product No: PRN013699


Kit Contents

- A** 1 x Radiator Guard
- B** 4 x Rubber Bungs







Please repeat on both side




Please repeat on
both side






Please repeat on
both side






Pull fairing back and out to release from rubber bung location














Caution

Lay a towel or cloth on the ground to stop damaging the fairing




Installation Instructions



Caution

Remove fairing by rotating the complete panel underneath the bike







Do not fully remove.
Required gap of 3mm only

brembo



Ensure radiator guard
securely hooks over the
top lip of the radiator

A small diagram within a green-bordered box shows a cross-section of the radiator guard's top edge. A green arrow points downwards from the top lip of the radiator, indicating the correct placement of the guard's hook.




Ensure radiator guard
securely hooks over the
top lip of the radiator

The diagram shows a cross-section of the radiator guard and the radiator. A green arrow with three short lines behind it points downwards, indicating the direction of the hooking action. The radiator has a distinct top lip, and the guard is designed to fit over it.



Caution


Push radiator guard back against bolts before tightening






Caution

Install fairing by rotating the complete panel underneath the bike







Reverse Stages

9 - 1



ESSENTIAL CHECKS



It is recommended that periodic inspections are made to ensure that dirt and debris have not become trapped between the guard and the radiator/oil cooler. Such dirt and debris would reduce the cooling efficiency of the radiator/oil cooler.

It is recommended that periodic inspections are made to ensure that all fixings are fully tightened.