




Arctic-Cat Winch Mount

Winch Mount

PART # 100635

Kit Components:


Qty	Part Description
1.....	Mount Bracket
1.....	#100480 Converter mount (Optional/ <u>NOT</u> Included)



“FIGURE 1”

4-HOLE MOUNTED WINCH INSTALLATION INSTRUCTIONS:

1. Remove the (4) bolts and the wire mesh screen on the front of the ATV as shown in Figure 1.
2. Place the mounting plate into position and mount it to the ATV using the hardware that was removed from Step 1.
3. Using the hardware that was supplied with your winch, install your winch and the fairlead as shown in Figure 2. The bottom (2) bolts that mount the winch will go thru the fairlead, then the mount and then into the winch.
4. Using the instructions provided with your winch, wire accordingly.



“FIGURE 2”


2-HOLE MOUNTED WINCH INSTALLATION INSTRUCTIONS:

(NOTE: This option requires the additional purchase of the converter mount Part #100490)

1. Remove the (4) bolts and the wire mesh screen on the front of the ATV as shown in Figure 1.
2. Place the mounting plate into position and mount it to the ATV using the hardware that was removed from Step 1.
3. Install the optional Converter Mount part #100480 to the mount using the hardware that was supplied with the Converter Mount, as shown in Figure 3. The top (2) bolts that mount the converter mount will go thru the fairlead, then the mount, then the converter mount, and then into the winch.
4. Using the hardware that was supplied with your winch, install your winch to the Converter mount #100480 as shown in Figure 3.

(Note: Some winch motors may be on the opposite side. Make sure your cable comes out between the spool and mounting surface of you winch)

5. Using the instructions provided with your winch, wire accordingly.



“FIGURE 3”