


Bike	KTM 1090 Adventure	Part No.	RKT-85
Year	2017-Current	Fit Kit	Z039.10578
Notes	Where not supplied use original fittings. Remove original gaskets if fitted. Fits with panniers	dB Killer	Z028.20168 (TYPE Y)

Estimated Fitting Time: 60 Minutes



NO.	PART NO.	DESCRIPTION	QTY
1	RSC367	Serket Silencer	1
2	CP907	Connecting Pipe	1
Fit Kit - Z039.10578			
3	Z017.10078	M8 x 50mm Cap Head Bolt	1
4	Z026.20068	Alloy Bolt Finisher	1
5	Z017.12754	M8 x 30mm Washer	2
6	Z017.10062	M8 Nyloc Nut	1
7	Z017.10073	M8 x 25mm Cap Head Bolt	2
8	Z017.10831	M8 x 17mm Washer	2
9	Z015.31288	Mounting Bracket	1
10	Z026.20049	M8 x 5mm Alloy Spacer	2
11	Z028.10030	Rubber Coated Spring	2
12	Z017.10620	M6 x 12mm Button Head Bolt	2
13	Z017.12748	M6 Fibre Washer	4
14	Z028.20324	Heat Shield	1

E-MARK	BSAU 193a 1990/t3
DATE	04/12/17
ISSUE	00
AUTHORISED	M.Ydlibi

NOTE: ENSURE SCORPION SYSTEM IS CLEAR OF MOVING PARTS AND ALL ORIGINAL FUNCTIONS WORK CORRECTLY.


STAY CONNECTED TO RED POWER.

Bike	KTM 1090 Adventure	Part No.	RKT-85
Year	2017-Current	Fit Kit	Z039.10573
Notes	Where not supplied use original fittings. Remove original gaskets if fitted. Fits with panniers	dB Killer	Z028.20168 (TYPE Y)

Estimated Fitting Time: 60 Minutes

A) Remove original exhaust from bike, taking care to keep all original components in a safe place.

B) Refit Scorpion exhaust as per line diagram above.

C) When fitted take bike for a short ride to ensure all functions are correct.

D) When bike & exhaust are cool enough check all nuts and bolts are still secure.

Thank you for purchasing your Scorpion Silencer.

Care of your exhaust: Please refrain from cleaning silencer with heavy solvents or abrasives!

Vielen Dank Für den kauf eines Scorpion Schalldampfers! Pflegehinweis: Bitte verwenden Sie niemals Scheuermittel oder aggressive Reiniger zur Pflege Ihres Auspuffes!

Merci d'avoir choisi un echappement Scorpion.

Entretien de votre silencieux: Ne pas utiliser de solvants ou de produits abrasifs!

Muchas gracias por adquirir un Silencioso Scorpion. Le recomendamos no limpiar el silencioso con productos abrasivos o aquellos que contengan disolventes.



STAY CONNECTED TO RED POWER.