



VStream® Windscreen Installation and Owner's Manual N20407, N20408, N20409, N20410 and N20411 Harley-Davidson FLHT/FLHX 2014~ Quantum® hardcoated polycarbonate

# **Attention**




Special notes and cautionary measures which can prevent damage to the accessory or motorcycle.

#### Note:



Tips for facilitation of operation, control and adjustment, as well as maintenance work.



#### TOOLS REQUIRED:

T27 Torx Wrench

### PARTS LIST

#### Index Description

Qty.

Windshield, Quantum Hardcoated polycarbonate

**PREPARATION** 



Retain all fasteners, they will be reused.

- 1. Place motorcycle securely on its side stand.
- 2. Protect fender and fairing from damage that may be caused by dropped hardware or tools.

#### **INSTALLATION**

- 1. Remove the three screws holding the stock windscreen in place. (T27 Torx Wrench) Figure 1
- 2. Remove the stock windscreen.
- 3. Install the VStream® windscreen. Figure 2
- 4. Install stock screws and tighten firmly. Do Not Overtighten. (T27 Torx Wrench)
- 5. Register your windscreen. Refer to page 2.



Figure 1



Figure 2



Edge is encapsulated by the rubber.



Trim Rubber stuck between inner and outer fairing.

©2014 National Cycle, Inc. PO Box 158, Maywood, IL 60153-0158 USA 708-343-0400 / Fax: 708-343-0625 / www.nationalcycle.com / e mail: info@nationalcycle.com

#### **MAINTENANCE**

**Cleaning:** Wash with a clean soft cloth, plenty of warm water and, if necessary, a non-abrasive soap such as dishwashing liquid. Flannel or soft chamois make good cleaning cloths. Do not use rain protective products on the screen due to the solvent action of the alcohol in these products. Do not allow brake fluid, alcohol, or strong solvents to contact the screen.

National Cycle Windshield Wash Part number N1401-01 is recommended for everyday cleaning. Product is supplied with a handy travel size container and rag for easy storage on the motorcycle. Ask your local dealer or visit: www.nationalcycle.com

# **A** WARNING

Never ride your motorcycle with loose accessory mounting hardware. Check the hardware for tightness regularly.

Today's motorcycles are built with enough frame rigidity to withstand the moderate loads imposed on them by the foreseeable addition of an accessory(ies). If an accessory(ies) adversely affects your motorcycle's stability, immediately remove the accessory(ies). Do not ride a motorcycle that exhibits unsafe handling traits.

Have experienced service personnel correct any problem before riding with the accessory(ies) installed. For further questions concerning handling problems associated with an accessory(ies), contact your dealer, motorcycle manufacturer, or accessory manufacturer.

Sunlight reflected off the inside curvature of the windscreen can, at certain times of day, cause extreme heat buildup on the motor- cycle's instruments and possibly even melt them. Exercise care in parking to avoid this. Park your motorcycle facing the sun or place an opaque object over this area.

# **National Cycle 3-Year Limited Warranty**



#### Register your windshield on Line at: www.nationalcycle.com/register.html

National Cycle hereby warrants to the original registered owner of a National Cycle polycarbonate windshield for a period of three years from the date of purchase against breakage. This limited warranty is expressly limited to the replacement of the polycarbonate windscreen. This limited warranty does not include scratches, coating failure, cosmetic wear and tear, replacement of hardware, or any consequential damages or expenses including labor cost of installation, removal and/or replacement, inconvenience, inbound freight expenses or damage to any other component of the motorcycle or any other accessories. Certain chemicals, generally known as acidic hydrocarbons, are known to cause polycarbonate damage and will not be covered under this limited warranty. Please refer to the cleaning instructions supplied with all National Cycle windshields.



Transparent dark tint Quantum® hard coated polycarbonate allows the beauty of your engine to shine through while blocking the heat. Heat Deflectors are available through your local dealer or visit our web site.



©2014 National Cycle, Inc. PO Box 158, Maywood, IL 60153-0158 USA 708-343-0400 / Fax: 708-343-0625 / www.nationalcycle.com / e mail: info@nationalcycle.com