

Denali Solo Guage Mount Speedometer

Triumph Bonneville, Thruxton & Scrambler

MBK.11.10100 Instructions Rev:00

PLEASE READ BEFORE INSTALLING

TWISTED THROTTLE products should be installed by a qualified, experienced motorcycle technician. If you are unsure of your ability to properly install a product, please have the product installed by your local motorcycle dealer. TWISTED THROTTLE takes no responsibility for damages caused by improper installation.


All screws, bolts, and nuts, including all replacement hardware provided by TWISTED THROTTLE should be tightened to the torque specified in the OEM maintenance manual for your motorcycle. If no torque specifications are provided in the OEM maintenance manual, the following torques may be used:

M5	3.5 ft-lbs (5 Nm)
M6	7 ft-lbs (9.6 Nm)
M8	13 ft-lbs (18 Nm)


All screws, bolts, and nuts should be checked after driving the first 30 miles (50 km) to ensure that all are tightened to the proper torque.

Medium strength liquid thread-locker (i.e., "Locktite") should be used to secure all screws, bolts, and nuts.


Distributed by:	
Twisted Throttle LLC	phone: 855.255.5550
570 Nooseneck Hill Rd	fax: 401.223.6955
Exeter, RI 02822	www.twistedthrottle.com



Installation Instructions











Step One: Remove the OEM Guage cluster from the top side of the upper tripple tree. Next install the speedometer to the new mounting bracket (#1), there is enough room in the housing to also hide the connector from the tachometer. Use the supplied hardware to mount the speedometer to the underside of the upper tripple tree. Note if you have stock handlebars you will need to use four spacers and the longer bolts to gain clearance. If the bike is equiped with clip-on's, only two spacers and the shorter bolts will be required.

